

Municipality of North Perth North Perth WWTP Master Plan Update and Small Communities Fund Application















Presentation to Council December 15, 2014 (amended December 17, 2014)







Wastewater Treatment Master Plan

Jan. 2012: Study Commencement Stakeholder Notifications issued

May 2012: Study Design Report completed

June 2014: Draft Master Plan report

Oct. 2014: Updated Master Plan

Nov. 2014: Meeting with MOECC

Dec. 2014: Consultation with Stakeholders


Feb. 2015: Public Information Centre

Winter 2015: Finalize Master Plan report






Small Communities Fund Application



The Small Communities Fund (SCF) will provide \$1 billion for projects in municipalities with fewer than 100,000 residents.





North Perth Wastewater Treatment Critical Upgrade Project

Item	Description	Cost (\$ million)
1.	Hwy 23 Sewage Pumping Station	\$ 0.9
2.	New Influent Forcemain	\$ 2.5
3.	Headworks Facility	\$ 3.0
4.	Lagoon Upgrades	\$ 1.5
5.	Sludge Management	\$ 4.0
6.	Tertiary Filtration and Disinfection	\$ 0.5
7.	SCADA	\$ 0.1
8.	Power Supply	\$ 1.0
(incl	Total: uding engineering, project management and taxes)	\$ 13.5 million



1. Hwy 23 Sewage Pumping Station

Description

Failure of pump station would result in spill of raw sewage into Middle Maitland River

- Install screening/grinding equipment to improve pump reliability, reduce clogging and minimize risks associated with manual cleaning by staff.
- Upgrade HVAC equipment
- Upgrade fuel storage/delivery equipment












2. New Influent Forcemain

Description

- Existing forcemain is becoming plugged with grease and debris, reducing capacity
- Failure of forcemain could result in release of sewage into environment

- Construct second forcemain
- Rehabilitate and clean existing forcemain to extend life








3. Headworks Facility

Description

- The existing facility is 21 years old and nearing the end of its useful service life
- Manual course bar screen is labour intensive, and ineffective at capturing debris
- No redundancy
- Excessive grease in plant influent causes performance issues downstream.

- Enclose headworks in building
- Replace manual bar screen with dual automated fine screens
- Construct new flow splitting chamber, second inlet channel and second grit chamber
- Replace undersized grit classiifer
- Remove fats, oils and grease at headworks
- Combine headworks facility with biosolids management facility







4. Lagoon Upgrades

Description

- East Lagoon is full of accumulated sludge, posing a liability for Municipality
- West Lagoon is used as wet weather flow buffer and normal secondary effluent polishing, and requires redundancy
- Old flow distribution chambers and piping between lagoons in need of immediate repair



- Decommission portion of east lagoon
- Divide West Lagoon into two cells for redundancy, including upgrades to flow distribution chambers
- Decommission old abandoned structures





5. Sludge Management

Description

- Aerobic digester at end of useful life
- Sludge storage does not meet MOECC guidelines
- No redundancy in digester and storage basin
- Sludge operations produce nuisance odours

- Construct two new concrete lined aerobic digesters
- Improve sludge management and operation, and install sludge thickener
- Expand sludge storage for additional capacity









6. Tertiary Filtration and Disinfection

Description

- Existing filters cannot handle peak flow capacity
- Filters near end of useful life
- UV disinfection equipment at end of useful life

Proposed Work

- Rebuild tertiary filters to restore original flow capacity
- Upgrade equipment for improved performance, operation and reliability

 Install new UV disinfection equipment








7. SCADA System

Description

 Existing SCADA has limited secondary data storage and security

Proposed Work

 New generation SCADA with additional monitoring and control capabilities, and increased data security









8. Power Supply

Power Supply

- Existing power supply and substation nearing capacity
- Plant not equipped with emergency standby power. Prolonged power failure could compromise effluent quality





- Optimize energy management and install high efficiency equipment to maximize capacity of existing power system and substation
- Complete upgrades to existing substation to extend useful life
- Install emergency standby power generator to ensure continued operation during power outages





Project Cost Timeline

Activity	2014-15	2015-16	2016-17	2017-18	2018-19	2019-20	TOTAL
Environmental Assessment	\$ 50,000						\$ 50,000
Design/ Engineering		\$ 869,400	\$ 372,600	\$ 210,000	\$ 210,000	\$ 210,000	\$ 1,872,000
Project Management		\$ 19,832	\$ 19,832	\$ 19,832	\$ 19,832	\$ 19,832	\$ 99,160
Construction			\$ 2,000,000	\$ 3,200,000	\$ 3,200,000	\$ 3,028,000	\$ 11,428,000
Communications Materials		\$ 7,910	\$ 3,390				\$ 11,300
Miscellaneous		\$ 11,300	\$ 11,300	\$ 11,300	\$ 11,300	\$ 11,300	\$ 56,500
Total Project Eligible Costs							\$ 13,516,960
Less Rebatable Tax Amount							\$ 1,344,494
Net Total Eligible							\$ 12,172,465
Total Requested Provincial Funding							\$ 1,966,766
Total Requested Federal Funding							\$ 1,966,766



- Submit SCF Funding Application
- Public Consultation
- Complete Master Plan
- Finalize Budgets
- Proceed with Detailed Design and Construction

